

Dredge Status:

Gov Mech @ RM 530

Channel Marker Status:

ATON: Light Stand at 396.6 has been destroyed. Red buoy is marking remaining rock pile.

Report ATON Discrepancies to:
SUMRWaterways@uscg.mil
319-520-8556

Hydro Survey Status:

Surveying in Pools 18, 22

Additional Risks / Concerns:

Nav Notice MR 16-6463-1
Mechanical Dredging
Cave Hollow, RM 305


Web Information:

For additional resources including
Navigation Notices:
<http://www2.mvr.usace.army.mil/NIC2/default.cfm>
Hydrographic Surveys and Dredging Schedule:
<http://www.mvr.usace.army.mil/Missions/Navigation/HydrographicSurveys.aspx>

KEY

- Surveyed Last Week
- Anticipated Dredging
- Groundings
- Dredge
- Very Likely to be Problematic at Low Water
- Could be Problematic at Low Water
- Problem Resolved

Probable "Hot" Spots	R. Mile	Min dep @ low water	Problem On:	Dredge ETA	Dredge Complete	Dredge
		305.0	9	L,R	14-Jun	13-Jul
	509.7	7.3	L	11-Jul		Gov Mech.



Dredge Status:

Gov Mechanical @ RM 136

Channel Marker Status:

Report ATON Discrepancies to:
SUMRWaterways@uscg.mil
319-520-8556

Hydro Survey Status:

Surveying in Starved Rock Pool

Additional Risks / Concerns:

NavNotice IW 15-1308-1 Upstream Mooring Cells

Nav Notice IW 16-6533 Scheduled Lock Closure July 7

Nav Notice IW 16-6572 Mechanical Dredging

Web Information:

For additional resources including
Navigation Notices:
<http://www2.mvr.usace.army.mil/NIC2/default.cfm>

Hydrographic Surveys and Dredging Schedule:
<http://www.mvr.usace.army.mil/Missions/Navigation/HydrographicSurveys.aspx>

KEY

- Surveyed Last Week
- Anticipated Dredging
- Groundings
- Dredge
- Very Likely to be Problematic at Low Water
- Could be Problematic at Low Water
- Problem Resolved

Probable "Hot" Spots	R. Mile	Min dep @ low water	Problem On:	Dredge ETA	Dredge Complete	Dredge
		136.0	8.9	L	6-Jul	14-Jul