

Dredge Status:
N/A

Channel Marker Status:
ATON: Light Stand at 396.6 has been destroyed. Red buoy is marking remaining rock pile.

Report ATON Discrepancies to:
SUMRWaterways@uscg.mil
319-520-8556

Hydro Survey Status:
Surveying in Pools 16-18


Additional Risks / Concerns:
Nav Notice MR 13-1834
Lock Restrictions LD15

Web Information:
For additional resources including
Navigation Notices:
<http://www2.mvr.usace.army.mil/NIC2/default.cfm>
Hydrographic Surveys and Dredging Schedule:
<http://www.mvr.usace.army.mil/Missions/Navigation/HydrographicSurveys.aspx>

KEY

- Surveyed Last Week
- Anticipated Dredging
- Groundings
- Dredge
- Very Likely to be Problematic at Low Water
- Could be Problematic at Low Water
- Problem Resolved

Probable "Hot" Spots	R. Mile	Min dep @ low water	Problem On:	Dredge ETA	Dredge Complete	Dredge
		305.0	9	L,R	31-May	



Dredge Status:

N/A

Channel Marker Status:

Report ATON Discrepancies to:
SUMRWaterways@uscg.mil
 319-520-8556

Hydro Survey Status:

Surveying near Havanna.

Additional Risks / Concerns:

NavNotice IW 15-1308-1
 Upstream Mooring Cells

Web Information:

For additional resources including
Navigation Notices:
<http://www2.mvr.usace.army.mil/NIC2/default.cfm>
Hydrographic Surveys and Dredging Schedule:
<http://www.mvr.usace.army.mil/Missions/Navigation/HydrographicSurveys.aspx>

Probable "Hot" Spots	R. Mile	Min dep @ low water	Problem On:	Dredge ETA	Dredge Complete	Dredge
	147.8	6'	LDB	TBD		Gov Mech