

UPPER MISSISSIPPI RIVER RESTORATION
LAKE ODESSA
HABITAT REHABILITATION AND ENHANCEMENT PROJECT

OPERATION AND MAINTENANCE MANUAL

APPENDIX F
PROJECT PHOTOGRAPHS

Table of Photographs

Photograph 1: Lake Odessa Habitat Rehabilitation and Enhancement Project Ribbon Cutting (USACE 2017)	1
Photograph 2: River Resources Coordinating Team Site Visit (Mitvalsky, USACE 2016).....	2
Photograph 3: Assistant Secretary of the Army Site Visit (USACE 2015)	2
Photograph 4: Inlet Channel Preconstruction (USACE 2001).....	4
Photograph 5: Inlet Channel Excavation and Sidecast Material (Mitvalsky, USACE 2016)	4
Photograph 6: Fields 4 and 5 Vegetation Prior to Flooding (Mitvalsky, USACE 2016).....	4
Photograph 7: Field 4 and 5 Vegetation Prior to Flooding (Mitvalsky, USACE 2016)	4
Photograph 8: Fields 4 and 5 Pump Pad Location (Mitvalsky, USACE 2016)	4
Photograph 9: Fields 4 and 5 Pump Pad (Mitvalsky, USACE 2017)	4
Photograph 10: Fields 4 and 5 Ditch (Mitvalsky, USACE 2016).....	5
Photograph 11: Little Goose Pond Pump Pad Location Pre-Project (USACE).....	5
Photograph 12: Little Goose Pond Pump Pad (Mitvalsky, USACE 2013).....	5
Photograph 13: Little Goose Pond Pump Pad (Bolser, USFWS 2017)	5
Photograph 14: Pre-Project Pumping Difficulties (USACE 2001).....	5
Photograph 15: Typical Temporary Pump, shown at Field 4 and 5 pump pad (Mitvalsky, USACE 2016) ..	5
Photograph 16: Temporary Pump Filling MSU (Mitvalsky, USACE 2005).....	6
Photograph 17: Muscatine Slough Water Control Structure (Bolser, USFWS 2017)	7
Photograph 18: Muscatine Slough Water Control Structure (Mitvalsky, USACE 2017).....	7
Photograph 19: Mallards Resting behind Muscatine Slough Water Control Structure (Mitvalsky, USACE 2017)	7
Photograph 20: Fox Pond Pre-Project (USACE 1995).....	7
Photograph 21: FWS MSU Pre-Project (USACE 1995).....	7
Photograph 22: Fox Pond at Water Control Structure (Mitvalsky, USACE 2016)	7
Photograph 23: Fox Pond Water Control Structure with Stoplogs Removed (Mitvalsky/USACE).....	8
Photograph 24: Fox Pond Water Control Structure Stoplogs in Place (Mitvalsky, USACE 2016).....	8
Photograph 25: Pelicans in Fox Pond (Mitvalsky, USACE 2016)	8
Photograph 26: Geese on Fox Pond (Bolser, USFWS 2016).....	8
Photograph 27: Snow Geese and Greater White-Fronted Geese Standing on a Mostly Frozen Fox Pond (Bolser, USFWS 2017)	8
Photograph 28: Mallards over Fox Pond (Bolser, USFWS 2016).....	8
Photograph 29: Northern Pintails at Louisa Division (Bolser, USFWS 2016).....	9
Photograph 30 Canada Geese, Sandhill Cranes, and Pelicans on the Louisa Division (Bolser, USFWS 2016)	9
Photograph 31: Solitary Sandpiper (Bolser, USFWS 2016).....	9
Photograph 32: Marsh Wren on Bulrush (Bolser, USFWS 2016)	9
Photograph 33: Mallards, Ring-Necked Ducks, Northern Pintails and Green-Winged Teal (Bolser, USFWS 2016).....	9
Photograph 34: Mallards at Louisa Division (Bolser, USFWS 2016).....	9
Photograph 35: Northern Waterthrush Observed With a Group of Warblers in a Willow Thicket (Bolser, USFWS 2016).....	10
Photograph 36: IADNR MSU Water Control on Outside of MSU (Mitvalsky, USACE 2016).....	10
Photograph 37: IADNR MSU Structure (Mitvalsky, USACE 2016)	10
Photograph 38: IADNR MSU Structure at Interior of MSU (Robbins, IADNR 2017).....	10

Photograph 39: IADNR MSU Final Grading (Mitvalsky, USACE 2012).....	10
Photograph 40: IADNR MSU after final grading (IADNR 2012).....	10
Photograph 41: IADNR MSU (Mitvalsky, USACE 2016).....	11
Photograph 42: IADNR MSU (Mitvalsky, USACE 2016).....	11
Photograph 43: Waterfowl use at Flooded IADNR MSU (Robbins, IADNR 2016).....	11
Photograph 44: Waterfowl Use at Flooded IADNR MSU (Robbins, IADNR 2016).....	11
Photograph 45: IADNR MSU Pump Pad Looking at Timber Stand Improvement Area (Mitvalsky, USACE 2011).....	11
Photograph 46: IADNR MSU Pump Pad Leading into Burris Ditch (Mitvalsky, USACE 2016).....	12
Photograph 47: View across proposed cuts from BeBee Pond, through BeBee/Swarms Cut, across Swarms Pond, through Swarms/Odesa Cut, across Lake Odessa and towards the bluff (USACE 2007).	12
Photograph 48: View across cuts from BeBee Pond Post Construction (Mitvalsky, USACE 2010)	12
Photograph 49: Floating Excavator for Small Channel Cuts (Mitvalsky, USACE 2009)	12
Photograph 50: Lake Odessa/Swarms Pond Dredge Cut and Sidecast Area (Mitvalsky, USACE 2009) .	12
Photograph 51: Odessa/Swarms Cut Post Construction and Vegetated (Mitvalsky, USACE 2012).....	13
Photograph 52: Bebee Pond/Swarms Pond Placement Site (Mitvalsky USACE 2009).....	13
Photograph 53: BeBee Pond/Swarms Pond Placement Site (Mitvalsky, USACE 2009)	13
Photograph 54: Levee Pre-Project (USACE 1994).....	15
Photograph 55: Levee Pre-Project (USACE 1994).....	15
Photograph 56: Levee Pre-Project (USACE 1994).....	15
Photograph 57: Dredge for Levee Sand (USACE 2007)	15
Photograph 58: Sand Embankment (USACE 2007)	15
Photograph 59: Sand Embankment (USACE 2008)	16
Photograph 60: Levee Repairs (Mitvalsky, USACE 2008)	16
Photograph 61: Top of Levee before seeding (Mitvalsky, USACE 2012)	16
Photograph 62: Clay Cap preparation (USACE 2008)	16
Photograph 63: Coyote on Levee surrounded by floodwater (Mitvalsky, USACE 2011).....	16
Photograph 64: Clay Cap Preparation (Mitvalsky, USACE 2011).....	16
Photograph 65: Delivering Clay for Two Foot Clay Cap (Mitvalsky, USACE 2011)	17
Photograph 66: Excess Material Management (Mitvalsky, USACE 2011).....	17
Photograph 67: Smoothing Out Side Slopes after Clay Cap in Place (Mitvalsky, USACE 2011).....	17
Photograph 68: Levee Repairs Post Seeding (Robbins, IADNR 2016).....	17
Photograph 69: Restored Levee (Mitvalsky, USACE 2016)	17
Photograph 70: Breach Repairs near Inlet (Mitvalsky, USACE 2016).....	17
Photograph 71: Breach Repairs near Inlet (Mitvalsky, USACE 2016).....	18
Photograph 72: Riprap Providing Flood Protection (Mitvalsky, USACE 2017).....	18
Photograph 73: Outlet Structure Being Constructed and Adjacent Levee Pre-Project (USACE 1995)	18
Photograph 74: Erosion at Outlet after Sand Enhancement and the 2008 Flood (USACE 2008)	18
Photograph 75: Riprap at Outlet Structure (USACE 2009)	18
Photograph 76: Riprap at Outlet Structure (USACE 2009)	18
Photograph 77: Low Water Crossing at Inlet (Harper, USACE 2012).....	19
Photograph 78: Low Water Crossing at Inlet with Gate (Harper, USACE 2011)	19
Photograph 79: Temporary Crossing near outlet (Mitvalsky, USACE 2015)	19
Photograph 80: Temporary Crossing near Outlet (Mitvalsky, USACE 2015)	19
Photograph 81: Mississippi River Spillway (Mitvalsky, USACE 2016).....	19
Photograph 82: Mississippi River Spillway Access Road around Structure (Mitvalsky, USACE 2016)..	19
Photograph 83: Iowa River Upstream Spillway (Mitvalsky, USACE 2016).....	20

Photograph 84: Iowa River Downstream Spillway (Mitvalsky, USACE 2016).....	20
Photograph 85: Iowa River Spillway Overtopping (USACE 2008)	20
Photograph 86: Iowa River Spillway Overtopping (USACE 2011)	20
Photograph 87: Iowa River Spillway Overtopping (Robbins, IADNR 2011)	20
Photograph 88: Iowa River Spillway Overtopping (Robbins, IADNR 2011)	20
Photograph 89: Iowa River Spillway Starting to Overtop (Robbins, IADNR 9/29/2016).....	21
Photograph 90: Iowa River Spillway Overtopping (Robbins, IADNR 9/30/2016)	21
Photograph 91: Iowa River Spillway Overtopping (Robbins, IADNR 10/3/2016)	21
Photograph 92: New (Upstream) Iowa River Spillway Overtopping (Robbins, IADNR 9/30/2016)	21
Photograph 93: New (Upstream) Iowa River Spillway Overtopping (Robbins, IADNR 10/3/2016)	22
Photograph 94: Mississippi River Spillway (Robbins, IADNR 9/30/2016).....	22
Photograph 95: Ephemeral Wetland (Robbins, IADNR 2012).....	24
Photograph 96: Ephemeral Wetland (Robbins, IADNR 2012).....	24
Photograph 97: Ephemeral Wetland (Robbins, IADNR 2012).....	24
Photograph 98: Diamondback Water Snakes (Robbins, IADNR 2016)	24
Photograph 99: Diamondback Water Snakes (Robbins, IADNR 2016)	24
Photograph 100: Water Snake at Outlet Structure (Mitvalsky, USACE 2016)	24
Photograph 101: Interior Wetland (Mitvalsky, USACE 2013).....	25
Photograph 102: Interior Wetland (Mitvalsky, USACE 2013).....	25
Photograph 103: Fisheries (Robbins, IADNR 2016)	27
Photograph 104: Sanitation (Harper, USACE 2010)	27
Photograph 105: Upper Goose Pond Cut (Mitvalsky, USACE 2010)	27
Photograph 106: Upper Goose Pond Placement (Mitvalsky, USACE 2010)	27
Photograph 107: Lower Goose Pond Placement (Mitvalsky, USACE 2010).....	27
Photograph 108: Lower Goose Pond in Water Placement (Mitvalsky, USACE 2010).....	28
Photograph 109: Middle Goose Pond Placement (Mitvalsky, USACE 2011).....	28
Photograph 110: Goose Pond Cut Off Berm (Mitvalsky, USACE 2012).....	28
Photograph 112: BeBee Pond Cut (Mitvalsky, USACE 2010).....	28
Photograph 113: Blackhawk Chute Yankee Chute (Mitvalsky, USACE 2008)	28
Photograph 114: Blackhawk Chute Yankee Chute (Mitvalsky, USACE 2008)	29
Photograph 115: South End of Blackhawk Chute (Mitvalsky, USACE 2010).....	29
Photograph 116: South End of Blackhawk Chute with placement sites on each side (Mitvalsky, USACE 2017)	29
Photograph 117: North End of Blackhawk/Yankee Chute with Alignment Stakes (Mitvalsky, USACE 2010)	29
Photograph 118: North End of Blackhawk/Yankee Chute Tree Clearing in Preparation for Dredged Material Placement (Mitvalsky, USACE 2011)	29
Photograph 119: North End of Blackhawk Chute (Mitvalsky, USACE 2017).....	29
Photograph 120: Yankee Chute (Mitvalsky, USACE 2013)	30
Photograph 121: Blackhawk Chute Material Recovery (USACE 2007)	30
Photograph 122: Blackhawk Chute Material Recovery (USACE 2007)	30
Photograph 123: Blackhawk Chute Excavation (USACE 2007).....	30
Photograph 124: Flood Inundation Line (USACE 1995)	32
Photograph 125: Flood Line on Trees following the 2008 Flood (Mitvalsky, USACE 2009)	32
Photograph 126: Post Flood Stress Pre-Project (USACE 2002).....	32
Photograph 127: Tree Planting (Harper, USACE 2010).....	32
Photograph 128: Tree Planting (Harper, USACE 2010).....	32

Photograph 129: Timber Stand Improvement Locations (Mitvalsky, USACE 2011)	32
Photograph 130: Floodplain Forest TIMBER STAND IMPROVEMENT Area (Mitvalsky, USACE 2016)	33
Photograph 131: Tree Planting (Lundh, USACE 2012)	33
Photograph 132: Timber Stand Improvement, Tree Girdling (Lundh, USACE).....	33
Photograph 133: Tree Planting (Lundh, USACE 2012)	33
Photograph 134: Selective Tree Clearing (Lundh, USACE 2012)	33
Photograph 135: Tree Planting (Lundh, USACE 2012)	33
Photograph 136: Tree Planting Site (Mitvalsky, USACE 2012)	34
Photograph 137: Tree Planting on Dredged Material Berms (Mitvalsky, USACE 2017)	34
Photograph 138: Fish Nursery Structure Original (USACE).....	36
Photograph 139: Fish Nursery Structure (Bolser, USFWS 2017)	36
Photograph 140: Fish Nursery Screw Gate (Bolser, USFWS 2017)	36
Photograph 141: Pre-Project Erosion Site 446 (Mitvalsky, USACE 2001).....	38
Photograph 142: Erosion Protection Site 446 (Robbins, IADNR 2017).....	38
Photograph 143: Site 98 & 99 riprap only (Mitvalsky, USACE 2008)	38
Photograph 144: Site 98 & 98 Riprap and Sand Protection (Mitvalsky, USACE 2009).....	38
Photograph 145: Site 98 & 99 erosion protection (Mitvalsky, USACE 2009).....	38
Photograph 146: Recreational Use at Archeological Site Post Construction (Mitvalsky, USACE 2012). 38	
Photograph 147: Site 424 Erosion Protection (Mitvalsky, USACE 2009)	39
Photograph 148: Site 300 (Mitvalsky, USACE 2017).....	39
Photograph 149: Erosion Protection Site 30 (Robbins, IADNR 2017).....	39
Photograph 150: Erosion Protection Site 30 (Robbins, IADNR 2017)	39
Photograph 151: Site 299 (Mitvalsky, USACE 2017).....	39
Photograph 152: Site 423 (Mitvalsky, USACE 2017).....	39
Photograph 153: Erosion Protection Site 27 (Mitvalsky, USACE 2017)	40
Photograph 154: Ribbon Cutting Site Visit (2017).....	42
Photograph 155: Ribbon Cutting Site Visit (2017).....	42
Photograph 156: Ribbon Cutting Site Visit (2017).....	42
Photograph 157: IANDR (Robbins, Griffin) Observing Final Site (2016).....	42
Photograph 158: Fox Pond Lookout (2016)	42
Photograph 159: USFWS Refuge Manager Cathy Nigg (2016).....	42
Photograph 160: Tree Clearing for Breach Repairs (2016)	43
Photograph 161: Spillway Construction Oversight (2015).....	43
Photograph 162: Spillway Construction (2015).....	43
Photograph 163: Assistant Secretary of the Army Site Visit (2015)	43
Photograph 164: 2014 Flood Damage Assessment with USFWS and USACE (2014).....	43
Photograph 165: 2014 Levee Breach Assessment (2014).....	43
Photograph 166: Levee Monument Discovered in Levee Breach (2013).....	44
Photograph 167: 2013 Flood Damage Assessment by Boat in Flooded Interior (2013)	44
Photograph 168: 2013 Levee Damage Assessment (2013).....	44
Photograph 169: 2013 Flood Damage Assessment (2013).....	44
Photograph 170: Mississippi River Levee Breach near Outlet (USACE 2013)	44
Photograph 171: Debris and Levee Damage (2013).....	44
Photograph 172: 2011 Flood Damage Assessment (2011).....	45
Photograph 173: Recreational Use at Archeological Site Following Protection (2011).....	45
Photograph 174: Contractor's Off Site Borrow Location (2012)	45

Photograph 175: Clay Cap Work near Dredge Cut (2011).....	45
Photograph 176: Extra Sam from Clay Cap Preparation (2011).....	45
Photograph 177: Levee Grading (2011).....	45
Photograph 178: In Water Placement Sites (2011).....	46
Photograph 179: Forest Assessment (2010).....	46
Photograph 180: Connecting Channels (2009).....	46
Photograph 181: IADNR Review of Water Conditions (2008).....	46
Photograph 182: Construction Oversight (2008).....	46
Photograph 183: 2008 Flood Damage Assessment (2008).....	46
Photograph 184: Public Involvement in Site Observations (2008).....	47
Photograph 185: 2008 Flood Damage Assessment (2008).....	47
Photograph 186: Spillway Construction (2007).....	47
Photograph 187: Spillway Construction (2006).....	47
Photograph 188: Project Engineers (2006).....	47
Photograph 189: Multiagency Review of Proposed Features (2006)	47
Photograph 190: Pump Inspection (2006)	48
Photograph 191: USFWS Refuge Manager Tom Cox (2006)	48
Photograph 192: USFWS Spillway (2005).....	48
Photograph 193: Constructing the USFWS Spillway (2004)	48
Photograph 194: Forestry Meeting (2002).....	48
Photograph 195: Forestry Meeting (2002).....	48
Photograph 196: Initial Survey (2001).....	49
Photograph 197: 2001 Flood Damage Assessment (2001).....	49
Photograph 198: Hydraulic Engineer Review of Water Control Structures (2001)	49
Photograph 199: Snake with a Copper Belly (2001)	49
Photograph 200: 2001 Flood Damage Assessment (2001).....	49
Photograph 201: IANDR Observing Trees (2000)	50
Photograph 202: Inlet Structure (2000)	50
Photograph 203: 1993 Flood Damage Assessment (1995).....	50
Photograph 204: 1993 Flood Damage Assessment (1995).....	50
Photograph 205: 1993 Flood Damage Assessment (1995).....	50
Photograph 206: 1993 Flood Damage Assessment (1995).....	51
Photograph 207: Early Planning Meetings (1995).....	51



Photograph 1: Lake Odessa Habitat Rehabilitation and Enhancement Project Ribbon Cutting (USACE 2017)



Photograph 2: River Resources Coordinating Team Site Visit (Mitvalsky, USACE 2016)



Photograph 3: Assistant Secretary of the Army Site Visit (USACE 2015)

Lake Odessa HREP Moist Soil Unit (MSU) Water Level Management



Photograph 4: Inlet Channel Preconstruction (USACE 2001)



Photograph 5: Inlet Channel Excavation and Sidecast Material (Mitvalsky, USACE 2016)



Photograph 6: Fields 4 and 5 Vegetation Prior to Flooding (Mitvalsky, USACE 2016)



Photograph 7: Field 4 and 5 Vegetation Prior to Flooding (Mitvalsky, USACE 2016)



Photograph 8: Fields 4 and 5 Pump Pad Location (Mitvalsky, USACE 2016)



Photograph 9: Fields 4 and 5 Pump Pad (Mitvalsky, USACE 2017)



**Photograph 10: Fields 4 and 5 Ditch
(Mitvalsky, USACE 2016)**



**Photograph 13: Little Goose Pond Pump Pad
(Bolser, USFWS 2017)**



**Photograph 11: Little Goose Pond Pump Pad
Location Pre-Project (USACE)**



**Photograph 14: Pre-Project Pumping
Difficulties (USACE 2001)**



**Photograph 12: Little Goose Pond Pump Pad
(Mitvalsky, USACE 2013)**



**Photograph 15: Typical Temporary Pump,
shown at Field 4 and 5 pump pad (Mitvalsky,
USACE 2016)**



Photograph 16: Temporary Pump Filling MSU (Mitvalsky, USACE 2005)



Photograph 17: Muscatine Slough Water Control Structure (Bolser, USFWS 2017)



Photograph 18: Muscatine Slough Water Control Structure (Mitvalsky, USACE 2017)



Photograph 19: Mallards Resting behind Muscatine Slough Water Control Structure (Mitvalsky, USACE 2017)



Photograph 20: Fox Pond Pre-Project (USACE 1995)



Photograph 21: FWS MSU Pre-Project (USACE 1995)



Photograph 22: Fox Pond at Water Control Structure (Mitvalsky, USACE 2016)



Photograph 23: Fox Pond Water Control Structure with Stoplogs Removed (Mitvalsky/USACE)



Photograph 26: Geese on Fox Pond (Bolser, USFWS 2016)



Photograph 24: Fox Pond Water Control Structure Stoplogs in Place (Mitvalsky, USACE 2016)



Photograph 27: Snow Geese and Greater White-Fronted Geese Standing on a Mostly Frozen Fox Pond (Bolser, USFWS 2017)



Photograph 25: Pelicans in Fox Pond (Mitvalsky, USACE 2016)



Photograph 28: Mallards over Fox Pond (Bolser, USFWS 2016)



Photograph 29. Northern Pintails at Louisa Division (Bolser, USFWS 2016)



Photograph 32: Marsh Wren on Bulrush (Bolser, USFWS 2016)




Photograph 30 Canada Geese, Sandhill Cranes, and Pelicans on the Louisa Division (Bolser, USFWS 2016)



Photograph 33: Mallards, Ring-Necked Ducks, Northern Pintails and Green-Winged Teal (Bolser, USFWS 2016)



Photograph 31: Solitary Sandpiper (Bolser, USFWS 2016)



Photograph 34: Mallards at Louisa Division (Bolser, USFWS 2016)



Photograph 35: Northern Waterthrush Observed With a Group of Warblers in a Willow Thicket (Bolser, USFWS 2016)



Photograph 38: IADNR MSU Structure at Interior of MSU (Robbins, IADNR 2017)



Photograph 36: IADNR MSU Water Control on Outside of MSU (Mitvalsky, USACE 2016)



Photograph 39: IADNR MSU Final Grading (Mitvalsky, USACE 2012)



Photograph 37: IADNR MSU Structure (Mitvalsky, USACE 2016)



Photograph 40: IADNR MSU after final grading (IADNR 2012)



Photograph 41: IADNR MSU (Mitvalsky, USACE 2016)




Photograph 42: IADNR MSU (Mitvalsky, USACE 2016)



Photograph 43: Waterfowl use at Flooded IADNR MSU (Robbins, IADNR 2016)



Photograph 44: Waterfowl Use at Flooded IADNR MSU (Robbins, IADNR 2016)



Photograph 45: IADNR MSU Pump Pad Looking at Timber Stand Improvement Area (Mitvalsky, USACE 2011)



Photograph 46: IADNR MSU Pump Pad Leading into Burris Ditch (Mitvalsky, USACE 2016)



Photograph 47: View across proposed cuts from BeBee Pond, through BeBee/Swarms Cut, across Swarms Pond, through Swarms/Odessa Cut, across Lake Odessa and towards the bluff (USACE 2007)



Photograph 48: View across cuts from BeBee Pond Post Construction (Mitvalsky, USACE 2010)



Photograph 49: Floating Excavator for Small Channel Cuts (Mitvalsky, USACE 2009)



Photograph 50: Lake Odessa/Swarms Pond Dredge Cut and Sidecast Area (Mitvalsky, USACE 2009)



Photograph 51: Odessa/Swarms Cut Post Construction and Vegetated (Mitvalsky, USACE 2012)



Photograph 52: BeBee Pond/Swarms Pond Placement Site (Mitvalsky USACE 2009)



Photograph 53: BeBee Pond/Swarms Pond Placement Site (Mitvalsky, USACE 2009)

Lake Odessa HREP Levee Restoration



Photograph 54: Levee Pre-Project (USACE 1994)



Photograph 55: Levee Pre-Project (USACE 1994)



Photograph 56: Levee Pre-Project (USACE 1994)



Photograph 57: Dredge for Levee Sand (USACE 2007)



Photograph 58: Sand Embankment (USACE 2007)



Photograph 59: Sand Embankment (USACE 2008)



Photograph 62: Clay Cap preparation (USACE 2008)



Photograph 60: Levee Repairs (Mitvalsky, USACE 2008)



Photograph 63: Coyote on Levee surrounded by floodwater (Mitvalsky, USACE 2011)



Photograph 61: Top of Levee before seeding (Mitvalsky, USACE 2012)



Photograph 64: Clay Cap Preparation (Mitvalsky, USACE 2011)



Photograph 65: Delivering Clay for Two Foot Clay Cap (Mitvalsky, USACE 2011)



Photograph 66: Excess Material Management (Mitvalsky, USACE 2011)



Photograph 67: Smoothing Out Side Slopes after Clay Cap in Place (Mitvalsky, USACE 2011)



Photograph 68: Levee Repairs Post Seeding (Robbins, IADNR 2016)



Photograph 69: Restored Levee (Mitvalsky, USACE 2016)



Photograph 70: Breach Repairs near Inlet (Mitvalsky, USACE 2016)



**Photograph 71: Breach Repairs near Inlet
(Mitvalsky, USACE 2016)**



**Photograph 74: Erosion at Outlet after Sand
Enhancement and the 2008 Flood (USACE
2008)**



**Photograph 72: Riprap Providing Flood
Protection (Mitvalsky, USACE 2017)**



**Photograph 75: Riprap at Outlet Structure
(USACE 2009)**



**Photograph 73: Outlet Structure Being
Constructed and Adjacent Levee Pre-Project
(USACE 1995)**



**Photograph 76: Riprap at Outlet Structure
(USACE 2009)**



Photograph 77: Low Water Crossing at Inlet (Harper, USACE 2012)



Photograph 80: Temporary Crossing near Outlet (Mitvalsky, USACE 2015)



Photograph 78: Low Water Crossing at Inlet with Gate (Harper, USACE 2011)



Photograph 81: Mississippi River Spillway (Mitvalsky, USACE 2016)



Photograph 79: Temporary Crossing near outlet (Mitvalsky, USACE 2015)



Photograph 82: Mississippi River Spillway Access Road around Structure (Mitvalsky, USACE 2016)



Photograph 83: Iowa River Upstream Spillway (Mitvalsky, USACE 2016)



Photograph 86: Iowa River Spillway Overtopping (USACE 2011)



Photograph 84: Iowa River Downstream Spillway (Mitvalsky, USACE 2016)



Photograph 87: Iowa River Spillway Overtopping (Robbins, IADNR 2011)




Photograph 85: Iowa River Spillway Overtopping (USACE 2008)



Photograph 88: Iowa River Spillway Overtopping (Robbins, IADNR 2011)



Photograph 89: Iowa River Spillway Starting to Overtop (Robbins, IADNR 9/29/2016)



Photograph 91: Iowa River Spillway Overtopping (Robbins, IADNR 10/3/2016)



Photograph 90: Iowa River Spillway Overtopping (Robbins, IADNR 9/30/2016)



Photograph 92: New (Upstream) Iowa River Spillway Overtopping (Robbins, IADNR 9/30/2016)



**Photograph 93: New (Upstream) Iowa River
Spillway Overtopping (Robbins, IADNR
10/3/2016)**



**Photograph 94: Mississippi River Spillway
(Robbins, IADNR 9/30/2016)**

Lake Odessa HREP Ephemeral Wetlands



**Photograph 95: Ephemeral Wetland
(Robbins, IADNR 2012)**



**Photograph 96: Ephemeral Wetland
(Robbins, IADNR 2012)**




**Photograph 97: Ephemeral Wetland
(Robbins, IADNR 2012)**



**Photograph 98: Diamondback Water Snakes
(Robbins, IADNR 2016)**



**Photograph 99: Diamondback Water Snakes
(Robbins, IADNR 2016)**



**Photograph 100: Water Snake at Outlet
Structure (Mitvalsky, USACE 2016)**



**Photograph 101: Interior Wetland
(Mitvalsky, USACE 2013)**



**Photograph 102: Interior Wetland
(Mitvalsky, USACE 2013)**

Lake Odessa HREP

Aquatic Diversity

Fisheries Enhancement



Photograph 103: Fisheries (Robbins, IADNR 2016)



Photograph 104: Sanitation (Harper, USACE 2010)



Photograph 105: Upper Goose Pond Cut (Mitvalsky, USACE 2010)



Photograph 106: Upper Goose Pond Placement (Mitvalsky, USACE 2010)



Photograph 107: Lower Goose Pond Placement (Mitvalsky, USACE 2010)



Photograph 108: Lower Goose Pond in Water Placement (Mitvalsky, USACE 2010)




Photograph 111: Goose Pond Berm Shaping to Control Top Height (Mitvalsky, USACE 2011)



Photograph 109: Middle Goose Pond Placement (Mitvalsky, USACE 2011)



Photograph 112: BeBee Pond Cut (Mitvalsky, USACE 2010)



Photograph 110: Goose Pond Cut Off Berm (Mitvalsky, USACE 2012)



Photograph 113: Blackhawk Chute Yankee Chute (Mitvalsky, USACE 2008)



Photograph 114: Blackhawk Chute Yankee Chute (Mitvalsky, USACE 2008)



Photograph 117: North End of Blackhawk/Yankee Chute with Alignment Stakes (Mitvalsky, USACE 2010)



Photograph 115: South End of Blackhawk Chute (Mitvalsky, USACE 2010)



Photograph 118: North End of Blackhawk/Yankee Chute Tree Clearing in Preparation for Dredged Material Placement (Mitvalsky, USACE 2011)



Photograph 116: South End of Blackhawk Chute with placement sites on each side (Mitvalsky, USACE 2017)



Photograph 119: North End of Blackhawk Chute (Mitvalsky, USACE 2017)



Photograph 120: Yankee Chute (Mitvalsky, USACE 2013)



Photograph 123: Blackhawk Chute Excavation (USACE 2007)



Photograph 121: Blackhawk Chute Material Recovery (USACE 2007)



Photograph 122: Blackhawk Chute Material Recovery (USACE 2007)

Lake Odessa HREP Floodplain Forest



**Photograph 124: Flood Inundation Line
(USACE 1995)**



**Photograph 127: Tree Planting (Harper,
USACE 2010)**



**Photograph 125: Flood Line on Trees
following the 2008 Flood (Mitvalsky, USACE
2009)**



**Photograph 128: Tree Planting (Harper,
USACE 2010)**



**Photograph 126: Post Flood Stress Pre-
Project (USACE 2002)**



**Photograph 129: Timber Stand
Improvement Locations (Mitvalsky, USACE
2011)**



Photograph 130: Floodplain Forest TIMBER STAND IMPROVEMENT Area (Mitvalsky, USACE 2016)



Photograph 133: Tree Planting (Lundh, USACE 2012)



Photograph 131: Tree Planting (Lundh, USACE 2012)



Photograph 134: Selective Tree Clearing (Lundh, USACE 2012)



Photograph 132: Timber Stand Improvement, Tree Girdling (Lundh, USACE)



Photograph 135: Tree Planting (Lundh, USACE 2012)



**Photograph 136: Tree Planting Site
(Mitvalsky, USACE 2012)**



**Photograph 137: Tree Planting on Dredged
Material Berms (Mitvalsky, USACE 2017)**

Lake Odessa HREP Fish Nursery



**Photograph 138: Fish Nursery Structure
Original (USACE)**



**Photograph 139: Fish Nursery Structure
(Bolser, USFWS 2017)**



**Photograph 140: Fish Nursery Screw Gate
(Bolser, USFWS 2017)**

Lake Odessa HREP Shoreline Protection of Historic Sites



Photograph 141: Pre-Project Erosion Site 446 (Mitvalsky, USACE 2001)



Photograph 144: Site 98 & 98 Riprap and Sand Protection (Mitvalsky, USACE 2009)



Photograph 142: Erosion Protection Site 446 (Robbins, IADNR 2017)



Photograph 145: Site 98 & 99 erosion protection (Mitvalsky, USACE 2009)



Photograph 143: Site 98 & 99 riprap only (Mitvalsky, USACE 2008)



Photograph 146: Recreational Use at Archeological Site Post Construction (Mitvalsky, USACE 2012)



**Photograph 147: Site 424 Erosion Protection
(Mitvalsky, USACE 2009)**



**Photograph 148: Site 300 (Mitvalsky,
USACE 2017)**



**Photograph 149: Erosion Protection Site 30
(Robbins, IADNR 2017)**



**Photograph 150: Erosion Protection Site 30
(Robbins, IADNR 2017)**



**Photograph 151: Site 299 (Mitvalsky,
USACE 2017)**



**Photograph 152: Site 423 (Mitvalsky,
USACE 2017)**



**Photograph 153: Erosion Protection Site 27
(Mitvalsky, USACE 2017)**

LAKE ODESSA HREP PLANNING, DESIGN, CONSTRUCTION, AND FLOODS



Photograph 154: Ribbon Cutting Site Visit (2017)



Photograph 157: IANDR (Robbins, Griffin) Observing Final Site (2016)



Photograph 155: Ribbon Cutting Site Visit (2017)



Photograph 158: Fox Pond Lookout (2016)



Photograph 156: Ribbon Cutting Site Visit (2017)



Photograph 159: USFWS Refuge Manager Cathy Nigg (2016)



Photograph 160: Tree Clearing for Breach Repairs (2016)



Photograph 163: Assistant Secretary of the Army Site Visit (2015)



Photograph 161: Spillway Construction Oversight (2015)



Photograph 164: 2014 Flood Damage Assessment with USFWS and USACE (2014)



Photograph 162: Spillway Construction (2015)



Photograph 165: 2014 Levee Breach Assessment (2014)



Photograph 166: Levee Monument Discovered in Levee Breach (2013)



Photograph 169: 2013 Flood Damage Assessment (2013)



Photograph 167: 2013 Flood Damage Assessment by Boat in Flooded Interior (2013)



Photograph 170: Mississippi River Levee Breach near Outlet (USACE 2013)



Photograph 168: 2013 Levee Damage Assessment (2013)



Photograph 171: Debris and Levee Damage (2013)



Photograph 172: 2011 Flood Damage Assessment (2011)



Photograph 175: Clay Cap Work near Dredge Cut (2011)



Photograph 173: Recreational Use at Archeological Site Following Protection (2011)




Photograph 176: Extra Sam from Clay Cap Preparation (2011)



Photograph 174: Contractor's Off Site Borrow Location (2012)



Photograph 177: Levee Grading (2011)



Photograph 178: In Water Placement Sites (2011)



Photograph 181: IADNR Review of Water Conditions (2008)



Photograph 179: Forest Assessment (2010)



Photograph 182: Construction Oversight (2008)



Photograph 180: Connecting Channels (2009)



Photograph 183: 2008 Flood Damage Assessment (2008)



Photograph 184: Public Involvement in Site Observations (2008)



Photograph 187: Spillway Construction (2006)



Photograph 185: 2008 Flood Damage Assessment (2008)



Photograph 188: Project Engineers (2006)



Photograph 186: Spillway Construction (2007)



Photograph 189: Multiagency Review of Proposed Features (2006)



Photograph 190: Pump Inspection (2006)



Photograph 193: Constructing the USFWS Spillway (2004)



Photograph 191: USFWS Refuge Manager Tom Cox (2006)



Photograph 194: Forestry Meeting (2002)



Photograph 192: USFWS Spillway (2005)



Photograph 195: Forestry Meeting (2002)



Photograph 196: Initial Survey (2001)



Photograph 197: 2001 Flood Damage Assessment (2001)



Photograph 198: Hydraulic Engineer Review of Water Control Structures (2001)



Photograph 199: Snake with a Copper Belly (2001)



Photograph 200: 2001 Flood Damage Assessment (2001)



Photograph 201: IANDR Observing Trees (2000)



Photograph 202: Inlet Structure (2000)



Photograph 203: 1993 Flood Damage Assessment (1995)



Photograph 204: 1993 Flood Damage Assessment (1995)



Photograph 205: 1993 Flood Damage Assessment (1995)



Photograph 206: 1993 Flood Damage Assessment (1995)



Photograph 207: Early Planning Meetings (1995)

