

Dredge Status:

Gov Mechanical @ Lock 16 Aux Lock

Gov Mechanical @ RM 336.4

Channel Marker Status:

ATON: Light Stand at 396.6 has been destroyed. Red buoy is marking remaining rock pile.

Report ATON Discrepancies to:
SUMRWaterways@uscg.mil
319-520-8556

Hydro Survey Status:

Surveying in Pools 11 & 12

Additional Risks / Concerns:

Nav Notice MR 16-6688-1
Diving Mussel Survey
Pool 15, RM 486 LDB and RDB

Nav Notice MR 16-6856
Scheduled Lock Closure
31 August


Nav Notice MR 16-6858
Scheduled Lock Closures
29 & 30 August

Nav Notice MR 16-6830
Mechanical Dredging RM 336

Web Information:

For additional resources including
Navigation Notices:
<http://www2.mvr.usace.army.mil/NIC2/default.cfm>

Hydrographic Surveys and Dredging Schedule:
<http://www.mvr.usace.army.mil/Missions/Navigation/HydrographicSurveys.aspx>



Dredge Status:

Gov Mechanical @ RM 271.0

Channel Marker Status:

Report ATON Discrepancies to:
SUMRWaterways@uscg.mil
 319-520-8556

Hydro Survey Status:

Surveying Marseilles and La Grange Pools

Additional Risks / Concerns:

Nav Notice IW 16-6787-2
 Mechanical Dredging
 Dresden Lower RM 270.9

Web Information:

For additional resources including
Navigation Notices:
<http://www2.mvr.usace.army.mil/NIC2/default.cfm>
Hydrographic Surveys and Dredging Schedule:
<http://www.mvr.usace.army.mil/Missions/Navigation/HydrographicSurveys.aspx>

Probable "Hot" Spots	R. Mile	Min dep @ low water	Problem On:	Dredge ETA	Dredge Complete	Dredge
	271.0	9	L	3-Aug	25-Aug	Gov Mech