

Dredge Status:

Gov Mechanical @ Lock 16 Aux Lock

Channel Marker Status:

ATON: Light Stand at 396.6 has been destroyed. Red buoy is marking remaining rock pile.

Report ATON Discrepancies to:
SUMRWaterways@uscg.mil
319-520-8556

Hydro Survey Status:

Surveying in Pools 11 & 12

Additional Risks / Concerns:

Nav Notice MR 16-6688-1
Diving Mussel Survey
Pool 15, RM 486 LDB and RDB

Nav Notice MR 16-6856
Scheduled Lock Closure
31 August

Web Information:

For additional resources including
Navigation Notices:
<http://www2.mvr.usace.army.mil/NIC2/default.cfm>

Hydrographic Surveys and Dredging Schedule:
<http://www.mvr.usace.army.mil/Missions/Navigation/HydrographicSurveys.aspx>


Nav Notice MR 13-11 1834
Lock Restrictions

Favor Reds

Favor REDS.
7.5' Shoal on apparent green buoy line.

ATON: Light Stand at 396.6 has been destroyed. Red buoy is marking remaining rock pile.

Nav Notice MR 16-6856
Scheduled Closure



Dredge Status:

Channel Marker Status:

Report ATON Discrepancies to:
SUMRWaterways@uscg.mil
319-520-8556

Hydro Survey Status:

Surveying Pool

Additional Risks / Concerns:

NavNotice IW 16-6898
Scheduled Lock Closure
7 SEPT 16

Web Information:

For additional resources including
Navigation Notices:
<http://www2.mvr.usace.army.mil/NIC2/default.cfm>

Hydrographic Surveys and Dredging Schedule:
<http://www.mvr.usace.army.mil/Missions/Navigation/HydrographicSurveys.aspx>

| Probable "Hot" Spots | R. Mile | Min dep @ low water | Problem On: | Dredge ETA | Dredge Complete | Dredge |
|----------------------|---------|---------------------|-------------|------------|-----------------|-------------|
| | 86.9 | 8 | R | 12-Sep | 25-Sep | Morgan Gale |