

Dredge Status:

Govt. Mech Plant 1 (767)
Status: Dredging @ Linwood, UMR RM 476.3
Next Job: Marais D'osier, Pool 14, UMR RM 510

Govt. Mech Plant 2 (766)
Status: Dredging @ Hogback, UMR RM 232.2
Next Job: TBD

Contract Mech
Status: Mobilizing

Govt. Hydraulic (Goetz)
Status: Demobilized

Channel Marker Status:

AIS AtoNs Broadcasting at:
486.5
330.7
301.9

Wyaconda:
Scioto:
Chyenne: Pools 20 to 22 this week.

Report ATON Discrepancies to:
SUMRWaterways@uscg.mil
or 319-520-8556

Additional Risks / Concerns:

Nav Notice MR 23-205443
Lock Restriction Lock 19
Upper River Wall Damage
UMR RM 364.2

Nav Notice MR 26-213855
Mechanical Dredging
Linwood, UMR RM 475.7-476.2

Nav Notice MR 26-213855
Mechanical Dredging
Hogback, UMR RM 330.7-332.2

Navigation chart update incoming.
New caution area at RM 308.2 along
railroad tracks due to unstable
embankment.

The linked surveys have been moved to the chart.
River miles in chart that are underlined have surveys
linked. Depending on Adobe versions the hyperlink
may need to be copied.

*For full survey list, please see eHydro

Buoyed 300' wide on bend. LW depths of 7.6 on RD, 9.2 mid channel and 7.9 on LD. 250' wide at 9' contour.

Narrow. Buoyed 300' wide in bend, 250' at 9' contour.

Cross channel shoaling. LW depths 8.3'

Narrow. LW depths of 8.2 on RD, 10.1 mid channel and 9.4 on LD. 270' wide at 9' contour, 150' wide at 10' contour.

Mechanical Dredging: Cross channel shoaling. LW depths of 8.6 on RD, 7.7 mid channel and 7.1 on LD.

RM 424.4: Cross channel shoaling. LW depths of 7.9'.
RM 427.0: Cross channel shoaling. Buoyed 220' wide. LW depths of 8.4'


Shoaling on LD. LW depths of 8.6' on LD. 285' wide.

Cross channel shoaling. LW Depths 8.7'

Mechanical Dredging: Spotty cross channel shoaling

Cross channel shoaling. LW depths of 7.4'. 200' wide.

Shoaling along new mooring chell. Depths of 5.5' at flat pool. Virtual ATONS broadcasting along the shoal.



Dredge Status:

Govt. Mechanical Plant
Status: Completed Bulls Island IWW RM 241
Next Job: Huse Slough IWW RM 219.0

Contract Mechanical
Status: Demobilized

Contract Hydraulic
Status: Demobilized

Dredge Goetz
Status: Demobilized

Channel Marker Status:

AIS ATOns Broadcasting at:

Sangamon: Buoy run complete.

Report ATOn Discrepancies to:
SUMRWaterways@uscg.mil
or **319-520-8556**

Additional Risks / Concerns:

Nav Notice IW 26-214228
Lock Restrictions, Brandon Rd.
IWW RM 286.0. July 3 @ 7:00pm to
July 4 @ 12:30am

Nav Notice IW 26-212839
Lock Advisory, Marseilles Lock
IWW RM 244.6

Nav Notice IW 26-214469
Lock Closure, Starved Rock Lock,
IWW RM 231.0, 25 June 2026, 0600
to 1800hrs.

The linked surveys have been moved to the chart. River miles in chart that are underlined have surveys linked, just click on the river mile to open survey. See eHydro for full survey list. Depending on Adobe versions the hyperlink may need to be copied.